

A20 alarm

The alarm A20 appears on the MCZ pellet stoves when there is a problem with the auxiliary sensor. The auxiliary sensor must be checked and, if necessary, replaced. This alarm can be triggered if the auxiliary sensor is short-circuited.

For this alarm a technician is often required.