

Communication louvers - E1000.10



The E1000.10 alarm appears on Rika pellet stoves when communication between the air vents and the motherboard is interrupted.

Solution

1. Let the stove cool down and unplug it from the power outlet
2. Disconnect the power supply for at least 10 seconds
3. Restore power
4. If the error reoccurs, a technician must be called. The "Communication Fault" error can also be caused by a broken cable or a short circuit