# Pressure switch not enough vacuum - E4000.02



The E4000.02 alarm appears on Rika pellet stoves when the pressure difference between the installation room and the combustion chamber is insufficient to resume operation.

## Solution

Check the stove for air leaks (firebox door, cleaning flap), disturbances in the room where the stove is installed (exhaust hood running, closed windows, etc.), and/or the chimney draft.

If the error message cannot be cleared, a technician must be called.