Alarm AL 03

The alarm AL 03 - REG. CODEUR appears on KLOVER pellet stoves when the flue gas fan does not run at the required speed.

This alarm often requires the intervention of a technician.