Flue Damper Open - E0200.08



The E0200.08 error code appears on Rika pellet stoves when the flue damper is not in the heating position.

Solution

1. Close the flue damper
2. Acknowledge the error message

If the error reoccurs, a technician must be called.