

Alarm AL 02

The alarm AL 02 - SMOKE TEMP. The alarm AL 02 - SMOKE TEMP. appears on KLOVER pellet stoves when there is a problem with the smoke temperature sensor. It is either faulty or disconnected.

This alarm often requires the intervention of a technician.