

Pressure sensor is not calibrated - E2000.10



The E2000.10 alarm appears on Rika pellet stoves when the pressure sensor's calibration value is invalid.

Solution

Carefully follow the on-screen instructions to reset the calibration value.