

Alarm A08

The A08 alarm appears on the MCZ pellet stoves when there is a fault on the smoke extraction fan. It can be a fan defect or a problem with the encoder (part that transmits the fan speed to the motherboard).

For this alarm a technician intervention is often necessary.